

NOT CONNECTED
OR
T. A. P.

WHITE/BLUE

BROWN



last revision date

file name

29-08-08

WD_EF8_M_0

EASY FAST CNG 8 CYLINDERS WIRING DIAGRAM


revision 000

Pag. 1/1

BROWN
PURPLE
GREEN

BROWN
PURPLE
GREEN


2



12


RED/BLACK

BROWN



10

BANK 1



BANK 2

WHITE/BLACK

YELLOW/BLACK

Oxygen Sensor 2

WHITE

YELLOW


Oxygen Sensor 1

BLACK

RPM signal

5

BANK 1




4

BANK 2

5

8



7

2	Reducer with CNG CUT-OFF valve
3	Manometer with level sensor
4	Filter with sensor
5	Injectors assembly
7	EASY FAST control unit
8	Harness
9	Switch
10	Injector harness
11	Self-diagnosis plug
12	Fuse 15 A