

NOT CONNECTED  
OR  
T. A. P.


WHITE/BLUE

BROWN

BROWN  
PURPLE  
GREEN

BROWN  
PURPLE  
GREEN

2




3

12

RED/BLACK

BROWN



9



11



last revision date

29-08-08

file name



WD\_EF6\_M\_0

# EASY FAST CNG 5-6 CYLINDERS WIRING DIAGRAM


revision 000

Pag. 1/1

8




7



BANK 1

5




4

BANK 1

5

10



BANK 1

BANK 2

WHITE/BLACK

YELLOW/BLACK

Oxygen Sensor 2

WHITE

YELLOW

Oxygen Sensor 1

BLACK

RPM signal

2	Reducer with CNG CUT-OFF valve
3	Manometer with level sensor
4	Filter with sensor
5	Injectors assembly
7	EASY FAST control unit
8	Harness
9	Switch
10	Injector harness
11	Self-diagnosis plug
12	Fuse 15 A